ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
DASARAHALLI

Ward No.
12

Ward Name
Shettihalli

Street ID
W0397, W0268, W0417, W0421, W0423

Street Name
V S T Opposite, 3rd Crs, NA, 2nd Crs

Significant Landmark
Abbigere Colony Surroundings

Segment No.
12/C-W0397/S020911

Total Length (m)
115.23

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	21.05	77.527142	13.071099	77.527102	13.070912	Abbigere Colony road	Abbigere main road
2	22.73	77.526554	13.071230	77.526517	13.071028	Abbigere Colony road	Abbigere Colony road
3	25.15	77.526149	13.071315	77.526102	13.071092	Abbigere Colony road	Abbigere Colony road
4	46.30	77.524497	13.070958	77.524406	13.070549	Abbigere Colony road	dead end

Work Details

History of Road / Lane / Circles

Name of the Work
Construction of Cement Concrete roads and Other Works in Abbigere Colony From 1st to 6th Cross in ward no-12 Shetty halli Sub Division

Sanctioned Estimated Amount (Rs.)
5000000

Sanctioned Year
2019

Year
2019 - 2020

Type of Work
Others

Other Work Type

Tender
Not a Tender

Work Details
Construction of Cement Concrete roads and Other Works in Abbigere Colony From 1st to 6th Cross in ward no-12 Shetty halli Sub Division

Job No. / Work Code
012-19-000013

Work Order No.
EE/DD/WO/438 /2019-20

Work Order Date
08/11/2019

Period of Extention

Defect Liability Period From
15/06/2020

Defect Liability Period To
14/06/2021

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)

Zone: DASARAHALLI **Ward No:** **Ward Name:** Shettihalli **Street ID:** W0397, W0268, W0417, W0421,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ವಾರ್ಡ್ ನಂ. 12, ಶೆಟ್ಟಿಹಳ್ಳಿ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು.

KRIDL 0.00

Phone No. E-Mail ID

9945044476

Field Inspection Details

Number of Trees	Any Other Information	Name
0		AP Shivakumar
Date of Inspection	**Remarks**	
30/11/2020		

Category	Image	Photo Remark
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Road Condition		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು/ಉಪವಿಭಾಗಾಧಿಕಾರಿ ಅಭಿಯಂತರರು

ವಾರ್ಡ್ ನಂ. 12, ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು. ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Zone: DASARAHALLI Ward No: 12 Ward Name: Shettihalli Street ID: W0397, W0268, W0417, W0421,